




DAMAGED SPRINKLERS



**The Bulb lost
its fluid....**







This head was removed from an existing approved system.

This is an extreme example of a sprinkler mishandled by the contractor, using wrong tools.

Yet it held



